

Mounting CPSET-M19



Required tools:

- 3, 4 and 6 mm Allen-type wrench
- 16 mm hexagonal wrench
- 17 mm hexagonal wrench
- Spirit level
- Electric drill with a 10 mm stone drill bit


Special settings for CPRT500/2-mx102/A1

- 4-Sensor Parallel-Muting
- Output „OSSD-state“ at M3 (parameter bit P0)
- Activation of internal start/restart interlock, start button at L5
- Muting time limit „infinite“



Leuze electronic GmbH + Co. KG
 In der Braike 1
 D-73277 Owen / Germany
 Phone +49 (0) 7021 / 573-0
 Telefax +49 (0) 7021 / 573-199
 info@leuze.de
 www.leuze.com

Procedure



1. The devices come already mounted in the UDC device column. The installation height can be adjusted by loosening the Allen screws of the device brackets in the column.
2. Find the midpoints for mounting the columns and mark them on the floor.
3. Starting at the midpoints, mark the connecting lines on the floor approx. 90 mm long.
4. Place the drill template on the midpoints and align it with the connecting lines. Mark the hole positions.
5. Drill mounting holes 80 mm deep and insert foundation bolts.
6. Set up the columns, screw them firmly into place and adjust roughly using the level (a). Using the adjustment screws (b), adjust the vertical position of the columns with the spirit level.
7. Fix MMS-A, the bracket with mounted muting sensors, on the vertical slot at the rear of the column.
8. Connect the muting sensors to the connection sockets X1 to X4 of the receiver, CPRT (as in figure below).
9. Connect yellow AS-i cable and black AS-i power supply cable to the AS-i adapter AC-PDA1/A and fix the adapter in the device column of the receiver.
10. Connect cable M12 5-pin to the machine interface /A1 and the AS-i adapter AC-PDA1/A.
11. Align sensor brackets (MMS-A) and muting sensors so that when activated at the same time, the opposing light scanners can safely distinguish between the transport material and people entering the danger area.
12. Switch on the devices and check that they are correctly aligned. Optimum alignment is achieved when the orange weak signal indicator on the receiver is no longer lit up.
13. Align muting sensors. The integrated muting lamp lights up when the opposing light scanner is activated at the same time.

